

| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|--------------------|------------|------------|-------|------------|--|----------|
| EDENBROOK MOTEL | NEWOWNER | 2018-05-16 | No | 9-A.(8) | Lights are not shielded in the laundry areas and the linen storage facilities. | N |
| EDENBROOK MOTEL | REGULAR | 2020-08-04 | No | | No Violations | |
| EDENBROOK MOTEL | REGULAR | 2023-08-01 | No | 4-A.(1) | Establishment is not in compliance with NFPA 101 Life Safety Code. | C |