

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
EDENBROOK MOTEL	NEWOWNER	2018-05-16	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
EDENBROOK MOTEL	REGULAR	2020-08-04	No		No Violations	
EDENBROOK MOTEL	REGULAR	2023-08-01	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C