

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
TWIN PONDS LODGE	REGULAR	2019-06-20	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				9-A.(6)	No Material Safety Data Sheet available on the premises.	N
TWIN PONDS LODGE	REGULAR	2019-06-20	No	3.C	Materials used for sewer connections are not semi-rigid, corrosion-resistant, non-absorbent, durable and water tight and/or sewer connections for seasonal campers not made with rigid pipe.	
TWIN POND LODGE	NEWOWNER	2022-07-20	No	3.E	Individual sewer risers not properly constructed / located / capped.	
				3.A.4	A current copy of the water analysis is not posted in the park in view of the public and/or the water has not been tested and shown to be satisfactory before the campground opens for the season.	
				7.D	There are no water supply outlets and/or water supply outlets are not backflow protected.	
				3.F.5	The floors, walls and ceiling of the sanitary building are not clean and in good repair and/or the toilets, lavatories and showers are not cleaned and disinfected daily and/or maintained in good repair.	
				3.F.6	The building is not free of objectionable odors.	
				9.A.5	Privy doors are not self-closing.	