

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
CAROLINA MOTEL (POOL)	REGULAR	2019-07-09	No	6.D.3	Ring buoy with throwing rope attached not provided, ring buoy is not US Coast Guard-approved with an outside diameter of 15 inches or greater, throwing rope for the ring buoy not of a minimum 1/4 inch diameter and/or throwing rope of ring buoy is not long enough (1.5 x width of pool) or 50 feet, whichever is less.	C
CAROLINA MOTEL (POOL)	REGULAR	2021-08-30	No	5.B.2	Flow meter not installed and/or is not accurate.	N
				6.F	Exposed piping not color coded or color coded correctly.	N
CAROLINA MOTEL (POOL)	NEWOWNER	2022-07-05	No	5.B.2	Flow meter not installed and/or is not accurate.	N
				5.D.3	A sign instructing users of the pool or spa to shower prior to entering the public pool or spa is not posted.	N