

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
SAINT JOHN RIVER RESORT	NEWOWNER	2022-02-28	No	10-B	Operating without a valid license issued by the Department.	N
				6-A.(6)	Hot and cold water under pressure are not provided at all sinks, lavatories, and/or dishwashers.	N
				2-A.(11)	Evidence of roaches, flies, vermin or other pests is present.	N
				9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-A.(1)	Sleeping rooms and bathrooms do not provide adequate lighting and/or adequate ventilation.	N
				2-A.(12)	The lodging establishment failed to wash, rinse and sanitize the cooking and multi-use eating and drinking tableware prior to use by succeeding guests.	C
				2-C.(2)	There is prohibited carpeting in a bath or toilet facility.	N
SAINT JOHN RIVER RESORT	FOLLOW_UP_FULL	2022-04-29	No	6-A.(6)	Hot and cold water under pressure are not provided at all sinks, lavatories, and/or dishwashers.	N
				2-A.(11)	Evidence of roaches, flies, vermin or other pests is present.	N
				2-A.(12)	The lodging establishment failed to wash, rinse and sanitize the cooking and multi-use eating and drinking tableware prior to use by succeeding guests.	C
SAINT JOHN RIVER RESORT	REGULAR	2022-10-17	No	9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				2-A.(3)	Where only natural ventilation is provided, outside openings are not adequately screened.	N
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N