

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
BREEZY ACRES MOTEL	REGULAR	2019-05-21	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-A.(1)	Sleeping rooms and bathrooms do not provide adequate lighting and/or adequate ventilation.	N
BREEZY ACRES MOTEL	NEWOWNER	2020-08-18	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-A.(1)	Sleeping rooms and bathrooms do not provide adequate lighting and/or adequate ventilation.	N