

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
ATLANTIC VIEW INN CORP	REGULAR	2018-06-27	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-B.(1)	The floors, walls, ceilings, windows and ventilation in common areas associated with sleeping rooms are not clean and/or not properly maintained.	N
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N
ATLANTIC VIEW INN CORP	REGULAR	2020-07-15	No	10-C	License not properly posted.	N
				10-B	Operating without a valid license issued by the Department.	N
				10-A.(1).a	Guest register is incomplete.	N
				9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-B.(1)	The floors, walls, ceilings, windows and ventilation in common areas associated with sleeping rooms are not clean and/or not properly maintained.	N
				2-A.(10)	Furniture, fixtures, carpets and other accessories are not maintained and/or are not clean.	N
				2-C.(7)	Toilet facilities, including the toilet room and fixtures, are not properly maintained, clean, adequately vented, and/or free of objectionable odors.	N
				2-C.(5)	An adequate supply of sanitary paper or cloth towels, or an approved hand drying device, is not available and conveniently located near the lavatory.	N
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N