

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
ROMAH MOTOR INN	REGULAR	2019-10-17	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
ROMAH MOTOR INN	NEWOWNER	2020-06-05	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-A.(14)	Appliances are not properly cleaned and/or not properly maintained.	N
				2-C.(7)	Toilet facilities, including the toilet room and fixtures, are not properly maintained, clean, adequately vented, and/or free of objectionable odors.	N
ROMAH MOTOR INN	REGULAR	2022-08-29	No	2-A.(8)	Torn and/or soiled bedding, mattresses, sheets or pillowcases are being used.	N
				2-C.(7)	Toilet facilities, including the toilet room and fixtures, are not properly maintained, clean, adequately vented, and/or free of objectionable odors.	N