

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
AROOSTOOK HOSPITALITY INN	REGULAR	2018-04-18	No	10-C	License not properly posted.	N
				2-A.(5)	Adequate artificial or mechanical ventilation not provided to rooms where natural ventilation is not possible.	N
AROOSTOOK HOSPITALITY INN	NEWOWNER	2021-11-23	No	10-B	Operating without a valid license issued by the Department.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
AROOSTOOK HOSPITALITY INN	REGULAR	2023-08-02	No	12-C	The potable water system is not installed to prevent the possibility of backflow and backsiphonage at all fixtures, equipment and faucets where hoses are attached.	C
				9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				2-A.(5)	Adequate artificial or mechanical ventilation not provided to rooms where natural ventilation is not possible.	N