

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
NORTHEASTERN MOTEL	REGULAR	2019-09-26	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C