

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
WHITE BIRCHES MOTEL	REGULAR	2019-02-05	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
WHITE BIRCHES MOTEL	REGULAR	2021-02-04	No		No Violations	
WHITE BIRCHES MOTEL	NEWOWNER	2022-06-09	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
WHITE BIRCHES MOTEL	REGULAR	2023-07-06	No	2-A.(3)	Where only natural ventilation is provided, outside openings are not adequately screened.	N