

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
THE MOORINGS INN WATERFRONT	REGULAR	2019-08-28	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
THE MOORINGS INN WATERFRONT	REGULAR	2022-09-28	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C