

| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|------------------------------|------------|------------|-------|------------|---|----------|
| HOWARD JOHNSON INN (POOL) | REGULAR | 2019-06-14 | No | 4.C.1 | Pedestrian access gate not self-closing, self-latching, opening outward, or can not accommodate a lock. | C |
| | | | | 5.B.2 | Flow meter not installed and/or is not accurate. | N |
| | | | | 6.B.1 | Rope and float line not present and/or not properly placed. | C |
| | | | | 5.D.3 | A sign instructing users of the pool or spa to shower prior to entering the public pool or spa is not posted. | N |