| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|------------------------|------------|------------|-------|------------|--|----------|
| HARRASEEKET INN (POOL) | REGULAR | 2020-11-12 | No | | No Violations | |
| HARRASEEKET INN (POOL) | REGULAR | 2023-05-10 | No | 3.A.2 | Public pool or spa establishment owner not retaining a pool or spa supervisor with CPO training and certification or equivalent. | С |
| HARRASEEKET INN (POOL) | NEWOWNER | 2023-06-05 | No | 5.B.2 | Flow meter not installed and/or is not accurate. | N |
| | | | | 5.B.1 | Pool data sheet not posted and/or does not contain required information. | N |
| | | | | 6.F | Exposed piping not color coded or color coded correctly. | N |
| | | | | 3.A.4 | Manufacturers instructions not available. | С |