

| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|--------------------|------------|------------|-------|------------|---|----------|
| RAMADA INN (POOL) | REGULAR | 2019-08-20 | No | 4.C.1 | Pedestrian access gate not self-closing, self-latching, opening outward, or can not accommodate a lock. | C |
| | | | | 5.B.2 | Flow meter not installed and/or is not accurate. | N |
| | | | | 6.C.8 | The edges of steps, ledges or seats do not have a 4-inch stripe of contrasting color. Stripe should be 2 inches on the thread and 2 inches on the riser. | C |
| | | | | 6.D.3 | Ring buoy with throwing rope attached not provided, ring buoy is not US Coast Guard-approved with an outside diameter of 15 inches or greater, throwing rope for the ring buoy not of a minimum 1/4 inch diameter and/or throwing rope of ring buoy is not long enough (1.5 x width of pool) or 50 feet, whichever is less. | C |
| RAMADA INN (POOL) | REGULAR | 2022-08-16 | No | 6.C.8 | The edges of steps, ledges or seats do not have a 4-inch stripe of contrasting color. Stripe should be 2 inches on the thread and 2 inches on the riser. | C |
| | | | | 6.C.1 | Depth markers not present, not conspicuously marked at or above the waterline, on the vertical pool wall, and/or on top of the coping, or on the edge of the deck or on the walk next to the pool. | C |
| | | | | 6.D.3 | Ring buoy with throwing rope attached not provided, ring buoy is not US Coast Guard-approved with an outside diameter of 15 inches or greater, throwing rope for the ring buoy not of a minimum 1/4 inch diameter and/or throwing rope of ring buoy is not long enough (1.5 x width of pool) or 50 feet, whichever is less. | C |