

| Establishment Name               | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation   | Severity |
|----------------------------------|------------|------------|-------|------------|--|----------|
| SHIRETOWN INN & SUITES<br>(POOL) | REGULAR    | 2019-06-18 | No    | 6.F        | Exposed piping not color coded or color coded correctly.   | N        |
|                                  |            |            |       | 6.C.8      | The edges of steps, ledges or seats do not have a 4-inch stripe of contrasting color. Stripe should be 2 inches on the thread and 2 inches on the riser. | C        |
|                                  |            |            |       | 6.E.2      | When required, SVRS or other approved system not installed.  | C        |
|                                  |            |            |       | 5.D.3      | A sign instructing users of the pool or spa to shower prior to entering the public pool or spa is not posted.  | N        |