

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
SPRUCE POINT INN RESORT & SPA (POOL)	REGULAR	2019-06-07	No		No Violations	
SPRUCE POINT INN RESORT & SPA (POOL)	REGULAR	2019-06-07	No	6.C.1	Depth markers not present, not conspicuously marked at or above the waterline, on the vertical pool wall, and/or on top of the coping, or on the edge of the deck or on the walk next to the pool.	C
SPRUCE POINT INN RESORT & SPA (POOL)	REGULAR	2021-05-26	No	5.B.1	Pool data sheet not posted and/or does not contain required information.	N
				3.A.3	Routine operating procedures not posted and/or available for viewing by the Department.	C
				6.G.1	Valves not tagged with metal or rigid plastic tags.	N
				6.F	Exposed piping not color coded or color coded correctly.	N
				6.C.7	Depth markers do not meet the 4 inch minimum height, are not a contrasting color to the background on which they are applied and/or not of a permanent nature.	C
SPRUCE POINT INN RESORT & SPA (POOL)	REGULAR	2021-06-03	No	5.B.1	Pool data sheet not posted and/or does not contain required information.	N
				3.A.3	Routine operating procedures not posted and/or available for viewing by the Department.	C
				6.G.1	Valves not tagged with metal or rigid plastic tags.	N
				6.F	Exposed piping not color coded or color coded correctly.	N
				6.C.7	Depth markers do not meet the 4 inch minimum height, are not a contrasting color to the background on which they are applied and/or not of a permanent nature.	C
				6.C.1	Depth markers not present, not conspicuously marked at or above the waterline, on the vertical pool wall, and/or on top of the coping, or on the edge of the deck or on the walk next to the pool.	C