| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|---------------------------------|------------|------------|-------|------------|--|----------|
| DOUBLE TREE BY HILTON (POOL) | REGULAR | 2019-07-10 | No | | No Violations | |
| DOUBLE TREE BY HILTON (POOL) | REGULAR | 2022-02-24 | No | 3.A.2 | Public pool or spa establishment owner not retaining a pool or spa supervisor with CPO training and certification or equivalent. | С |
| | | | | 5.B.2 | Flow meter not installed and/or is not accurate. | N |
| | | | | 5.B.1 | Pool data sheet not posted and/or does not contain required information. | N |
| | | | | 3.A.3 | Routine operating procedures not posted and/or available for viewing by the Department. | С |
| | | | | 6.G.1 | Valves not tagged with metal or rigid plastic tags. | N |
| DOUBLE TREE HOTEL (POOL) | NEWOWNER | 2023-08-08 | No | 5.B.2 | Flow meter not installed and/or is not accurate. | N |