

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
THE LODGE @ TURBATS CREEK (POOL)	REGULAR	2019-08-28	No	6.C.1	Depth markers not present, not conspicuously marked at or above the waterline, on the vertical pool wall, and/or on top of the coping, or on the edge of the deck or on the walk next to the pool.	C
THE LODGE @ TURBATS CREEK (POOL)	REGULAR	2023-08-09	No	5.B.2	Flow meter not installed and/or is not accurate.	N
				3.A.4	Manufacturers instructions not available.	C
				3.G.4	Material Safety Data Sheets not available for inspection.	N
				6.F	Exposed piping not color coded or color coded correctly.	N
				6.G.1	Valves not tagged with metal or rigid plastic tags.	N
				3.A.3	Routine operating procedures not posted and/or available for viewing by the Department.	C
				5.B.1	Pool data sheet not posted and/or does not contain required information.	N
				6.B.1	Rope and float line not present and/or not properly placed.	C