

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
THE LINCOLNVILLE MOTEL (POOL)	REGULAR	2018-06-11	No	6.C.2	Depth markers are not properly positioned to be read from the water side on a vertical pool wall.	C
				6.B.1	Rope and float line not present and/or not properly placed.	C