Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
RODEWAY INN	REGULAR	2018-02-23	No	12-D	Plumbing is unacceptable.	N
				5-A.(1)	lce is not made from potable water and/or is not located, installed, operated and maintained so as to prevent contamination of the ice.	N
				2-A.(3)	Where only natural ventilation is provided, outside openings are not adequately screened.	N
RODEWAY INN	REGULAR	2019-09-25	No	11-A.(3)	Screen doors to the outer air are not self-closing; and screens for windows, doors, skylights, transoms, and other openings to the outer air are not tight-fitting and free of breaks.	N
				9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				2-B.(2)	The furniture, fixtures, draperies, and other accessories in common areas associated with sleeping rooms are not clean and/or not properly maintained.	N
				2-A.(9)	The floors, walls, and ceilings of bedrooms, closets, and storage areas are not clean and/or not maintained.	N
				2-A.(14)	Appliances are not properly cleaned and/or not properly maintained.	N
HOME 2 SUITES	REGULAR	2023-07-21	No	4-101.19	Nonfood contact surfaces of equipment that requires frequent cleaning not constructed of a corrosion-resistant, nonabsorbent, and smooth material.	N
HOME 2 SUITES	REGULAR	2023-07-21	No	2-A.(8)	Torn and/or soiled bedding, mattresses, sheets or pillowcases are being used.	N