

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
SACO RIVER HIDEAWAY CAMPGROUND	NEWOWNER	2018-09-25	No	8.A.4	Plans submitted did not include specifications of the proposed park or area showing the number and location of RV and tenting sites.	
				7.D	There are no water supply outlets and/or water supply outlets are not backflow protected.	
				7.G	Plumbing is unacceptable.	
				3.F.5	The floors, walls and ceiling of the sanitary building are not clean and in good repair and/or the toilets, lavatories and showers are not cleaned and disinfected daily and/or maintained in good repair.	
				3.F.1	Inadequate number of facilities provided.	
				3.F	Service building not provided within 500 feet of all sites.	
				3.D	Dump station not provided, properly constructed, provided with suitable hinged cover and/or screw cap, provided with a water outlet posted with a sign that water from this outlet is not for drinking water purposes and/or not protected with an anti-siphon backflow preventer.	
SACO RIVER HIDEAWAY CAMPGROUND	REGULAR	2020-09-08	No	3.C	Materials used for sewer connections are not semi-rigid, corrosion-resistant, non-absorbent, durable and water tight and/or sewer connections for seasonal campers not made with rigid pipe.	
				3.F.5	The floors, walls and ceiling of the sanitary building are not clean and in good repair and/or the toilets, lavatories and showers are not cleaned and disinfected daily and/or maintained in good repair.	