

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
EAST VIEW MOTEL	REGULAR	2018-08-20	No	9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				9-A.(6)	No Material Safety Data Sheet available on the premises.	N
EAST VIEW MOTEL	REGULAR	2022-08-18	No	9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				9-A.(8)	Lights are not shielded in the laundry areas and the linen storage facilities.	N
				2-A.(10)	Furniture, fixtures, carpets and other accessories are not maintained and/or are not clean.	N
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N