

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
KATAHDIN VALLEY MOTEL	REGULAR	2019-05-16	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N
KATAHDIN VALLEY MOTEL	REGULAR	2021-05-20	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-A.(13)	Drinking glasses have not been washed and sanitized after each day of occupancy and/or clean glasses, not otherwise protected, are not inverted on a clean surface.	C
				2-C.(1)	Floors, walls, ceilings, and all fixtures in toilet and bath rooms are not smooth, durable and easily cleanable.	N
KATAHDIN VALLEY MOTEL	NEWOWNER	2023-08-01	No		No Violations	