

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
MILLIKEN HOUSE	REGULAR	2019-10-31	No		No Violations	
MILLIKEN HOUSE	REGULAR	2019-10-31	No	9-A.(2)	Clean linens and supplies are not properly stored in cabinets constructed to facilitate cleaning, on shelves at least 6 inches off the floor and/or in storage rooms that are kept clean.	N
				4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
MILLIKEN HOUSE	NEWOWNER	2021-05-14	No		No Violations	
MILLIKEN HOUSE	NEWOWNER	2021-05-14	No		No Violations	
MILLIKEN HOUSE	REGULAR	2024-03-14	No	6-201.16	Wall and ceiling coverings are not easily cleanable.	N
MILLIKEN HOUSE	REGULAR	2024-03-14	No	4-A.(1)	Establishment is not in compliance with NFPA 101 Life Safety Code.	C
				2-B.(1)	The floors, walls, ceilings, windows and ventilation in common areas associated with sleeping rooms are not clean and/or not properly maintained.	N