

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
POLAND SPRING CAMPGROUND (POOL)	REGULAR	2019-08-19	No	5.D.3	A sign instructing users of the pool or spa to shower prior to entering the public pool or spa is not posted.	N
POLAND SPRING CAMPGROUND (POOL)	NEWOWNER	2023-08-04	No	5.B.2	Flow meter not installed and/or is not accurate.	N
				6.F	Exposed piping not color coded or color coded correctly.	N
				6.C.8	The edges of steps, ledges or seats do not have a 4-inch stripe of contrasting color. Stripe should be 2 inches on the tread and 2 inches on the riser.	C
				6.D.3	Ring buoy with throwing rope attached not provided, ring buoy is not US Coast Guard-approved with an outside diameter of 15 inches or greater, throwing rope for the ring buoy not of a minimum 1/4 inch diameter and/or throwing rope of ring buoy is not long enough (1.5 x width of pool) or 50 feet, whichever is less.	C