

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
BARTLETT ST UNITS	REGULAR	2019-02-12	No	9-A.(6)	No Material Safety Data Sheet available on the premises.	N
				2-B.(1)	The floors, walls, ceilings, windows and ventilation in common areas associated with sleeping rooms are not clean and/or not properly maintained.	N