

Establishment Name	Insp. Type	Insp. Date	Fail?	Rule Cited	Description of Violation	Severity
BIRCH POINT LOG LODGE	REGULAR	2018-06-13	No	7.D.1	Individual water services are improperly located, designed, protected, or sized.	
				3.D	Dump station not provided, properly constructed, provided with suitable hinged cover and/or screw cap, provided with a water outlet posted with a sign that water from this outlet is not for drinking water purposes and/or not protected with an anti-siphon backflow preventer.	
BIRCH POINT CAMPGROUND	REGULAR	2021-07-13	No	8.A.4	Plans submitted did not include specifications of the proposed park or area showing the number and location of RV and tenting sites.	
				3.A.4	A current copy of the water analysis is not posted in the park in view of the public and/or the water has not been tested and shown to be satisfactory before the campground opens for the season.	
				7.D	There are no water supply outlets and/or water supply outlets are not backflow protected.	
				3.D	Dump station not provided, properly constructed, provided with suitable hinged cover and/or screw cap, provided with a water outlet posted with a sign that water from this outlet is not for drinking water purposes and/or not protected with an anti-siphon backflow preventer.	
BIRCH POINT CAMPGROUND	REGULAR	2023-08-23	No	8.A.4	Plans submitted did not include specifications of the proposed park or area showing the number and location of RV and tenting sites.	
				7.D	There are no water supply outlets and/or water supply outlets are not backflow protected.	