

| Establishment Name | Insp. Type | Insp. Date | Fail? | Rule Cited | Description of Violation | Severity |
|----------------------|------------|------------|-------|------------|--|----------|
| RIVERBEND CAMPGROUND | NEWOWNER | 2023-04-12 | No | 3.A.4 | A current copy of the water analysis is not posted in the park in view of the public and/or the water has not been tested and shown to be satisfactory before the campground opens for the season. | |
| | | | | 7.D | There are no water supply outlets and/or water supply outlets are not backflow protected. | |
| | | | | 3.F | Service building not provided within 500 feet of all sites. | |
| | | | | 3.D | Dump station not provided, properly constructed, provided with suitable hinged cover and/or screw cap, provided with a water outlet posted with a sign that water from this outlet is not for drinking water purposes and/or not protected with an anti-siphon backflow preventer. | |